

Fiber optic assembly kits

K1 + K2



Fiber optic assembly kit for FSMA connectors PCF (K1)

The fiber optic assembly kits K1 and K2 are the same except for the cleave tool and microscope adapter.

Order no.	Contents of the fiber optic assembly kit
Z004-TA0-0,5-2,2	Stripper for 230 µm PCF conductors
ZXXX-TN0	Kevlar scissors
ZSMA-TW0	Cleave tool – FSMA
00405402	Container for fiber off-cuts
ZXXX-TL0	Card cleaner
ZXXX-TF0-V1	Microscope, 100x magnification
ZSMA-AF0-V1	Microscope adapter

Order table

Suitable for Simplex FSMA connectors	Order no.
For PCF cables with buffered fiber Ø 2.2 mm	SSMA-SW0-02-0010
For PCF cables with buffered fiber Ø 3.0 mm	SSMA-SW0-02-0020
Fiber optic assembly kit	ZSMA-KW0

Fiber optic assembly kit for ST connectors PCF (K2)

The fiber optic assembly kits K1 and K2 are the same except for the cleave tool and microscope adapter.

Order no.	Contents of the fiber optic assembly kit
Z004-TA0-0,5-2,2	Stripper for 230 µm PCF conductors
ZXXX-TN0	Kevlar scissors
ZXST-TW0	Cleave tool – PCF ST
00405402	Container for fiber off-cuts
ZXXX-TL0	Card cleaner
ZXXX-TF0-V1	Microscope, 100x magnification
ZXST-AF0-V1	Microscope adapter

Order table

Suitable for Simplex ST connectors	Order no.
For PCF cables with buffered fiber Ø 2.2 mm	SXST-SW0-02-0010
For PCF cables with buffered fiber Ø 2.5 mm	SXST-SW0-02-0020
For PCF cables with buffered fiber Ø 3.0 mm	SXST-SW0-02-0030
Fiber optic assembly kit	ZXST-KW0